

StripAssay® Troubleshooting Guide



| Problem | Possible cause | Comments and suggested solutions | |
|--|--|---|--|
| Weak or missing WT and MUT signals, upper control line present | <u>Inefficient or failed amplification</u> | | |
| | Fragmented DNA | Repeat DNA extraction | |
| | Input DNA amount out of - usually below - the specified working range of the assay (10 to 50 ng in total per reaction) | Check DNA concentration; if concentration is too low repeat DNA extraction | |
| | Amplification failure due to presence of PCR inhibiting substances in DNA preparation | Re-purify DNA or dilute DNA with PCR grade water prior to PCR (use a concentration of at least 2 ng/µl). In case GEN ^X TRACT™ Resin or magnetic particles are present in DNA template, centrifuge 5 min at 12,000 rpm and use supernatant for PCR. | |
| | Incorrect Taq DNA Polymerase dilution (inappropriate dilution or dilution buffer or not freshly prepared) | Prepare fresh and correct Taq DNA Polymerase dilution in Taq Dilution Buffer supplied with the kit | |
| | Defective, low-quality or improper (e.g. hotstart) Taq DNA Polymerase | Use Taq DNA Polymerase provided by ViennaLab (TAQ-500, TAQ-2500) or other high-quality Taq DNA polymerase | |
| | Incorrect volumes of Amplification Mix, diluted Taq DNA Polymerase or DNA used in the assay | Use calibrated pipettes and carefully control the dispensed reagent volumes (see Instructions For Use) | |
| | Incorrect PCR program or unsuitable PCR tubes used | Verify PCR program, use suitable thin-wall PCR tubes | |
| | | <u>Low hybridization efficiency</u> | |
| | | Hybridization temperature too high (> 45°C) | Adjust temperature of hybridization device to exactly 45°C (+/- 1°C) and check temperature with calibrated external thermometer; fully submerge sensor of thermometer! |
| | Precipitates in Hybridization Buffer and Wash Solution A | Prewarm buffers to 45°C (+/- 1°C) and mix well to dissolve precipitates prior to use | |
| | Incorrect incubation time during hybridization steps | Do not prolong or shorten incubation times. Exactly follow the Instructions For Use | |
| All signals weak or missing, including upper control line | Systematic error in the protocol | Repeat assay according to Instructions For Use | |
| | Kit reagents expired, deteriorated or stored improperly | Repeat assay with fresh reagents | |

| Problem | Possible cause | Comments and suggested solutions |
|--|--|--|
| <p>Drop-out of WT and MUT signals for one marker</p> <p>Other markers show normal staining</p> | <p>Partial drop out of multiplex PCR due to thermoblock of PCR cyclers not preheated</p> | <p>Control PCR with gel electrophoresis. If amplicons are missing repeat PCR. Preheat thermoblock to specified temperature, only then insert PCR tubes into PCR cyclers.</p> |
| | <p>Special genetic situation, e.g. rare SNP or deletion present in the primer and / or probe binding site</p> | <p>Sequencing analysis of the sample is indicated</p> |
| <p>High background or presumptive false positive results</p> | <p>Input DNA amount above the specified working range of the assay (10 to 50 ng in total per reaction)</p> | <p>Check DNA concentration using OD 260 nm (e.g. Nanodrop) or fluorometric (e.g. Qubit)* DNA measurement, adjust to 2 to 10 ng/μl with PCR grade water</p> |
| | <p>Incorrect Taq DNA Polymerase dilution (inappropriate dilution or dilution buffer or not freshly prepared)</p> | <p>Prepare fresh and correct Taq DNA Polymerase dilution in Taq Dilution Buffer supplied with the kit</p> |
| | <p>PCR setup at room temperature</p> | <p>Use cold reagents and set up PCR on ice or cooling block</p> |
| | <p>Thermoblock of PCR cyclers not preheated</p> | <p>Preheat thermoblock to specified temperature, only then insert PCR tubes into PCR cyclers. Important note: oncology StripAssays® (BRAF, EGFR, KRAS, NRAS) PCR starts with 37°C</p> |
| | <p>Mix up of Wash Solution A and Wash Solution B (staining appears greenish)</p> | <p>Use correct reagents according to the Instructions For Use</p> |
| | <p>Hybridization temperature too low (< 45°C)</p> | <p>Adjust temperature of hybridization device to exactly 45°C (+/- 1°C) and check temperature with calibrated external thermometer; fully submerge sensor of thermometer!</p> |
| | <p>Insufficient heat transmission due to too low water level in the waterbath or incubation with open lid</p> | <p>Adjust water level to ½ of the height of the incubation tray; keep lid of waterbath closed to avoid temperature variations and evaporation</p> |
| | <p>Use of inappropriate hybridization device (e.g. air-based incubators)</p> | <p>Use shaking waterbath or recommended thermoshaker with heated lid (Biosan PST-60HL, Biosan PST-60HL-4)</p> |
| <p>Incorrect incubation time during hybridization steps</p> | <p>Do not prolong or shorten incubation times Exactly follow the Instructions For Use</p> | |
| <p>Untimely analysis of still wet Teststrips</p> | <p>Let Teststrips dry completely (avoid exposure to light) before interpretation of results</p> | |

| Problem | Possible cause | Comments and suggested solutions |
|--|--|--|
| Positive bands in no-template control (NTC) | DNA contamination of the NTC sample itself and/or PCR reagents and/or equipment | Carry out DNA extraction and PCR setup using filter-tips along with dedicated pipettes. Clean workbench and equipment; repeat assay with fresh reagents |
| | Cross-contamination of neighbouring lanes in the tray during hybridization | Apply moderate shaking frequency to avoid lane-to-lane spilling |
| Unstained areas along band pattern of the Teststrips | Teststrips placed face down into tray | Insert Teststrips with glossy side towards the bottom |
| | Incorrect volumes of detection reagents used | Use calibrated pipettes and carefully control the dispensed reagent volumes (see Instructions For Use) |
| High background staining of entire Teststrip(s) | Insufficient incubation with Wash Solution B | Carry out incubation according to the Instructions For Use |
| | Color development was not carried out shaking and/or reaction was exposed to direct light | Carry out all incubation steps on a shaking platform, avoiding exposure to light during color development |
| | Color development was carried out at high (> 25°C) room temperature | Reduce room temperature below 25°C |
| | Color Developer was insufficiently rinsed off | Rinse Teststrips several times with distilled water |
| Applies specifically to α-Globin StripAssay® (4-160): | | |
| PCR Control A and B missing, WT bands present | PCR products were hybridized to inappropriate Teststrip (Mix A1 + A2 to Teststrip B and Mix B to Teststrip A) | Repeat hybridization and add amplicons to corresponding Teststrip |
| PCR Control A missing | PCR products of Mix A2 were not hybridized to Teststrip A | Repeat hybridization and add amplicons to corresponding Teststrip |
| Difficulties to amplify -3.7del and anti-3.7 mutations | Input DNA amount too high and/or contamination with PCR inhibitors (particularly applies for magnetic-particle based extraction systems) | Dilute DNA with PCR grade water to 2 to 10 ng/ μ l prior to PCR |

| Problem | Possible cause | Comments and suggested solutions |
|--|---|---|
| Applies specifically to BRAF (5-560), KRAS (5-680), NRAS (5-620) and EGFR (5-630)-StripAssays®: | | |
| PCR Positive Control missing or very weak | Poor quality input DNA (degraded or containing inhibitors) | Repeat DNA extraction or re-purify DNA |
| | Input DNA amount below the specified working range of the assay (5 to 50 ng in total per reaction) | Check DNA concentration, using fluorometric DNA measurement (e.g. Qubit)*; if concentration is too low repeat DNA extraction. Important note: DNA extracted from formalin-fixed and paraffin embedded tissue (FFPE) cannot be quantified correctly using UV-VIS based methods (e.g. Nanodrop) |
| | Inhibition of Taq DNA Polymerase | Dilute DNA with PCR grade water |
| | Highly compromised DNA quality due to formalin fixation | Repeat DNA extraction |
| Faint background and / or PCR Negative Control signal present | Impaired blocking and resulting amplification of wild-type allele due to excessive DNA input amount | Check DNA concentration using fluorometric DNA measurement (e.g. Qubit)*, adjust to 1 to 10 ng/μl with PCR grade water. Important note: DNA extracted from formalin-fixed and paraffin embedded tissue (FFPE) cannot be quantified correctly using UV-VIS based methods (e.g. Nanodrop) |
| | Low quality of FFPE DNA contaminated with substances interfering with specificity of primers and wild-type-blocking | Avoid overloading FFPE DNA extraction columns; a diligent processing of FFPE material according to the manufacturer's protocol for DNA extraction ensures minimal carry-over of contaminants |
| | DNA samples from stained tissue (e.g. May Grünwald Giemsa) | Use unstained tissue material |
| | Formalin over-fixation of tissue samples and/or use of old or unbuffered formalin solution for fixation | Use fresh and neutral buffered formalin, avoid excessive fixation |
| | Ramp rate of thermocycler too low (< 1°C/sec). Excessive amount of template input may further increase background | Change ramp rate in thermocycler settings or use suitable instrument |


| Problem | Possible cause | Comments and suggested solutions |
|---|---|---|
| Unclear mutation signals | Weak signals may be the result of the presence of a low frequency mutation | Repeat PCR and hybridization. A mutation with low frequency present in the sample is reproducible. Within a range, the intensity of a mutation signal will change with the template amount used in PCR |
| | Multiple faint signals for variable mutations caused by insufficient DNA quality or deviation from the protocol | Consider purification of the original DNA. Check the DNA concentration, repeat PCR and hybridization. The faint pattern of formalin-induced artefacts is usually not reproducible |
| <p>* Please verify the use of the correct Qubit kit: 1X dsDNA BR (range 4 to 4000 ng), dsDNA BR (range 4 to 2000 ng) or (1X) dsDNA HS (range 0.1 to 120 ng) for DNA quantification.</p> | | |

General considerations:


1. Keep pre- and post-PCR workspace separated
2. Use suitable equipment (shaking waterbath or recommended thermoshaker)
3. Follow exactly the Instructions For Use

Examples of StripAssay® results:

5-680 KRAS XL StripAssay®



4-390 FMF-SAA1 StripAssay®



4-360 CVD StripAssay® T

